


# Instructions for Installation of Gloves In A Bottle Window Displays

- 1 Liberally apply window cleaner, soapy water or denatured alcohol onto the glass surface that the panels and graphics will be applied to. Be sure to thoroughly clean the entire surface of the window, edges and corners very carefully so that they are completely free of all dust, dirt and debris. This is especially important if you are placing any panel next to any window edges or corners.


Use a clean lint-free cloth to wipe the surface dry.



- 2 Use a water-soluble marker to draw guide lines on the opposite side of the glass that the panels and graphics are going to be installed on. You should use the scaled down sample template (please, see reverse side of this page) to help you properly position each panel, right & left drops as well as the bottle.



- 3 Fill a 24 oz spray bottle with a mixture of water and 3 drops of liquid dish detergent.




- 4 Spray down the surface of the window that the horizontal panel (Shielding Lotion...) will be applied to so it is completely misty with soapy water.

**Note Well:** Be sure all edges and corners are completely free of all dirt and matter before you position the horizontal panel.

- 5 Lay the horizontal panel on a clean flat surface and remove the liner to expose the adhesive side of the graphic.


**Caution** - do not get any dust or debris on the adhesive side of the panels or graphics.




- 6 You will need a second person to help you hold each of the 4 corners of the horizontal panel.

- 7 Be sure that the window is fully saturated with a mist of the soapy water mixture.

- 8 Carefully place each of the 4 corners of the horizontal panel into the proper position onto the window.



- 9 With one of your hands lightly pat down the panel from the center outward to all edges.



*Please, see reverse side for the sample template and further instructions...*